

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1588 West North Temple  
Salt Lake City, Utah 84116

JIM  
FEB 03 1982  
RECEIVED  
JAN 28 1982  
DIVISION OF  
OIL, GAS & MINING

1981 ANNUAL OPERATIONS AND PROGRESS REPORT

(To be filed for each Mining Operation  
at the end of each calander year)

OPERATOR: Minerals Recovery Corp. MINE NAME: John mine  
ADDRESS: 575 Union Blvd. #304 PERMIT NUMBER: DOE/019/010  
Lakewood, CO 80228 SEC. 1 T. 23S R. 21E SLBM  
REPRESENTATIVE: Dianna D. Evans DATE OF APPROVAL: 8/26/80

(1) Section 40-8-15 and Rule M-8 of the Utah Mined Land Reclamation Act,  
require each operator to include with this report and up-dated map and  
plan prepared in accordance with Rule M-3, providing a detailed status of  
all mining and reclamation activities which have occurred during the past  
year.

(2) The gross amount of materials moved during the year for this mining  
operation was: 360.45 Tons of ore and approximately 490 Tons of  
waste

The disposition of each type of material was: The ore was shipped off  
the property, and the waste is being stockpiled at the mine  
site.



(3) STATUS OF RECLAMATION WORK\*

<u>Month</u>	<u>Number of Acres</u>	<u>Type of Work Performed</u>	<u>Results (Revegetation Success)</u>
January	_____	_____	_____
February	_____	_____	_____
March	_____	_____	_____
April	_____	_____	_____
May	_____	_____	_____
June	_____	_____	_____
July	_____	_____	_____
August	_____	_____	_____
September	_____	_____	_____
October	_____	_____	_____
November	_____	_____	_____
December	_____	_____	_____

\*The monthly status of reclamation work should include such items as clean-up, regrading, recontouring, soil preparation, seeding, etc., and may be outlined on a separate sheet if necessary.

SEE ATTACHED SHEET., NOTE: THERE HAS NOT BEEN ANY CHANGES FROM THE ORIGINAL MAP SUBMITTED IN AUGUST, 1980, THEREFORE, IT IS NOT INCLUDED IN THIS REPORT. HOWEVER, ONE IS AVAILABLE UPON REQUEST.

John Mine, DOE/019/010

No reclamation was performed on this property during 1981, as the mining phase is still in progress. However the amount of disturbance has not increased since inception of the project. There were not any drill holes placed on this property in 1981.